Snohomish / Harvey Field / S43



Communications

Update: Aerial photo above does not depict grass runway built in 2001, taxiways built in 2002-2003, the removal of grove of trees to the west of the runways, and four hangars in the south hangar complex.

Navigation

Elevation: 16'

Latitude:...... N 47° 54.49′ Longitude:..... W 122° 06.32′

PCL:

Runway:......14/32; 2660'x36'; Asphalt

Lights:..... Dusk-dawn, NSTD

Indicator:...... Wind Obstacles: Powerlines

From City: 01 SW TPA:

Services

Fuel: A 100LL

Services: Major Airframe and

Power Plant

Manager:......360-568-1541

Notes

Right hand traffic on runway 14. Caution: Parachute operations.

Page 105